Delamination detection in a 90-year-old glulam block with scanning dry point-contact ultrasound

Journal Article

Author(s):

Neuenschwander, Jürg; Sanabria, Sergio J.; Schuetz, Philipp; Widmann, Robert; Vogel, Mareike

Publication date:

2013-12

Permanent link:

<https://doi.org/10.3929/ethz-b-000065369>

Rights / license:

[In Copyright - Non-Commercial Use Permitted](#)

Originally published in:

Holzforschung 67(8), <https://doi.org/10.1515/hf-2012-0202>

Jürg Neuenschwander*, Sergio J. Sanabria^a, Philipp Schuetz, Robert Widmann and Mareike Vogel

Delamination detection in a 90-year-old glulam block with scanning dry point-contact ultrasound

Abstract: Glued laminated timber (glulam) is known in timber constructions since more than 100 years. Glulam members can delaminate due to aging and excessive changes of temperature and humidity. This results in significantly reduced load bearing capability of the affected structural members. This contribution focuses on the ultrasonic point-contact inspection of gluing plane delamination as a nondestructive method. Ultrasonic measurements on a section of a 90-year-old roofing glulam member are presented. The results are compared with manual detection and evaluation of delamination with a feeler gauge, with X-ray computed tomography analyses, and with numerical simulations. Appropriate data evaluation of the mechanized ultrasonic results allows the determination of material separation that are deeper than 20 mm in the signature of the surface wave and large-scale delamination (>80% of the complete bonding width) in the back-wall echo. Numerical simulations based on the finite-difference time-domain method shed light into the details of the wave propagation and support the experimental findings.

Keywords: bonding quality, delamination, glue line, glued laminated timber, integrity assessment, nondestructive evaluation, point-contact ultrasonics, X-ray computed tomography

^aPresent address: Laboratory for Wood Physics and Non Destructive Testing Methods, Institute for Building Materials, ETH Zurich, Schafmattstrasse 6, CH-8093 Zurich, Switzerland

***Corresponding author: Jürg Neuenschwander**, Electronics/Metrology/Reliability Laboratory, Empa, Swiss Federal Laboratories for Materials Science and Technology, Überlandstrasse 129, CH-8600 Dübendorf, Switzerland, Phone: +41 58 765 4320, e-mail: juerg.neuenschwander@empa.ch

Sergio J. Sanabria and Philipp Schuetz: Electronics/Metrology/Reliability Laboratory, Empa, Swiss Federal Laboratories for Materials Science and Technology, Überlandstrasse 129, CH-8600 Dübendorf, Switzerland

Robert Widmann: Structural Engineering Research Laboratory, Empa, Swiss Federal Laboratories for Materials Science and Technology, Überlandstrasse 129, CH-8600 Dübendorf, Switzerland

Mareike Vogel: Architecture, Wood and Civil Engineering, Berne University of Applied Sciences, Solothurnstrasse 102, CH-2500 Biel 6, Switzerland

Introduction

Glued laminated timber (glulam) is widely used in the construction of roofing and bridges. Functionality is only given with a sound bonding along the glue line between laminations. Delamination, however, may occur due to improper manufacturing, moisture-induced internal stresses, and long-term loading (Hansson and Larson 2005; Jönsson 2005; Angst and Malo 2010; Bucur 2011). A recent study of 550 failure cases showed that 70% of them were due to cracks in the grain direction and 62% of them occurred at the glue lines (Blass and Frese 2010). The effects of climatic conditions on bondlines can also be demonstrated by nanoindentation (Konnerth and Gindl 2008; Follrich et al. 2010). Nondestructive quality control of the bonding is presently done by visual inspection and with thin feeler gauges (Dietsch and Hösl 2010). The performance of ultrasound-based nondestructive techniques has been improved in the last decade (Casado et al. 2012). Conventional ultrasonic contact transducers were used on glulam without coupling agent for the detection of large planar cracks and lamination defects (Dimanche et al. 1994; Dill-Langer et al. 2005). The depth of edge open cracks was estimated with stress wave timing by putting transmitter and receiver transducers on both sides of the crack (Garab et al. 2010; Divos 2011). Recent developments in ultrasonics have led to the application of nondestructive testing methods such as air-coupled scanning (Sanabria et al. 2011a,b,c; Sanabria 2012) or with dry point-contact ultrasound (Hasenstab 2006, 2007; Aicher et al. 2010; Sanabria et al. 2011c). X-ray computed tomography (CT) was applied on solid wood with cracking (Niemz et al. 1997), and it was possible differentiating between glued and delaminated regions in glued structures by CT (Hu and Gagnon 2007). Limited-angle microfocus CT is able to detect air gaps larger than 150 µm in the joint of 100 mm broad spruce lamellas (Sanabria et al. 2011d).

In the study of Sanabria et al. (2011c), a glulam test-block containing artificial flaws (partial absence of glue) was investigated with point-contact ultrasound and large flaws could be detected and imaged. Both the surface wave (SW) C-scan and the back-wall echo C-scan gave

defect indications. An advantage of this technique is the application of shear horizontal waves with excitation in the fiber direction because they exhibit a quasi-isotropic propagation within the RT plane of spruce (Sanabria et al. 2011c; Sanabria 2012).

In the present contribution, the point-contact ultrasonic technique is applied to the section of a glulam beam that was in service for nearly a century and exhibits considerable (natural) delamination. The ultrasonic results should be put into relation to inspections with a feeler gauge, X-ray CT, and numerical simulation of the wave propagation.

Materials and methods

Sample

An early application of glulam was found in the roofing support of an aircraft hangar that was erected in Lucerne, Switzerland, in 1922 (Figure 1). The whole structure was dismantled only recently. The glulam beams exhibit considerable delamination. The beam originally had been reinforced by external steel clamps, whose color remnants are still visible on the surface (Figure 2a). It was made of 14 lamellas from Norway spruce (*Picea abies* Karst.) that were glued together with a Casein adhesive. The dimensions of the cutout and inspected sample was as follows: length (Y direction) 1020 mm, width 146 mm, and height 384 mm. Moisture content: 11.5%; average oven-dried density ρ_0 : 380 kg m⁻³. The definition of the lateral sides I and II of the specimen and the lamella numbering are given in Figure 3a. The bottom-side lamellas (Nos. 1 and 2) had a height of 36 mm and the remaining lamellas (Nos. 3–14) had a height of 26 mm each. Delaminations that were accessible from the outside were measured manually with a 100- μ m-thick and 12-mm-wide feeler gauge. All glue lines were investigated on the lateral sides I and II. The position, length, and depth of the delaminations were recorded.

X-ray CT

A part of the specimen was inspected in a X-ray CT system equipped with a 450 kV X-ray tube. Detection: flat-panel detector (scintillator screen from thallium-doped cesium-iodide with a thickness of 2 mm; scintillation light recorded with a CCD camera, Alta U32 from Apogee Imaging Systems (Roseville, CA, USA), via a 45° mirror). Acceleration voltage of the source: 200 kV (current of 3.0 mA; during flat field acquisition, the current was 2.5 mA). A total of 720 projections with an integration time of 2.0 s each were acquired, where the sample was rotated by 0.5° between consecutive images. The reconstructed 3D absorption image has a resulting voxel size of 167×167×167 μ m³ and contains 1900×1900×1300 voxels.

Ultrasound setup

A dry point-contact ultrasonic probe was used in conjunction with a mechanical scanner (Figure 2); for details, see Sanabria et al. (2011c)

Figure 1 Photographs of aircraft hangar in Lucerne, Switzerland, erected in 1922. (a) View from the outside. (b) View from the inside: three glulam beams (arrows), reinforced with steel clamps, supporting the roof are visible. (c) Two glulam beams after dismantling of the construction.

and Sanabria (2012). Pulse-echo measurements: shear wave array transducer (M2502; Acoustic Control Systems Ltd., Moscow, Russia). The transducer (Hasenstab 2006) consists of two groups of 12 point elements, the first acting as a transmitter (Tx) and the second as a receiver (Rx). The two 12 point element groups are electrically connected, so that the same signal is excited in all of them (Tx) and the signals captured in each element are added up (Rx). The elements have ceramic tips and are spring loaded, allowing a defined contact force with the sample even in the case of surface irregularities. A specific scanning system was developed to perform automated lamination defect imaging in glulam. For each scanned position, the transducer was pressed down and then an ultrasound pulse was excited by the Tx and received by the Rx. Next, the transducer was moved up until there was no contact with the sample, and afterwards, it was moved to the next scanning position where the procedure was repeated. The transmitter Tx was excited with a high-voltage pulse (three 50 kHz

Figure 2 (a) Photograph of mechanical setup. Inspection of sample on side I. The longitudinal axis Y is indicated by an arrow. (b) Bottom view of point-contact ultrasound transducer.

cycles, Gaussian, 220 Vpp). The receiver Rx signal (A-scan) was amplified by 40 dB and band-pass filtered (10–100 kHz). The computerized scanning system achieved a high repeatability, with <10% amplitude error (Sanabria et al. 2011c).

The inspection was performed on the lateral surfaces side I and II. All bonding planes B1...B13 were tested individually by positioning all Tx elements on one side of the glue line and all the Rx elements on the other side. Profiles along the length of the beam ($Y=30$ –990 mm) were obtained by scanning the transducers with 5 mm steps in Y direction. The polarization vector $\mathbf{p}$ of the transducer elements was aligned with the fiber direction L (Y) to couple efficiently the shear wave horizontal mode. This mode is most attractive for wood inspection due to its low level of anisotropic energy flux shift from the defined normal insonification direction (Sanabria et al. 2011b; Sanabria 2012). For C-scan presentations, the positive maximum amplitude of the A-scan in the selected time gates was calculated and displayed as a 2D image. For the definitions of A-, B-, and C-scans, see standard EN 1330-4 (2010).

Numerical simulations

A 2D finite-difference time-domain simulation software was implemented in Matlab (Sanabria 2012). The simulations implement linear elastic wave propagation across selected cross-sections of the glulam beam. A specific rotated staggered grid, based on the article of Saenger et al. (2000), allows the stable discretization of air-solid boundaries by direct definition of material properties at each voxel. Pulsed wave propagation is discretized in the time domain with a staggered stress-particle velocity scheme. Perfect matched layers, based on Drossaert and Giannopoulos (2007), allow reducing the discretized air domain around the sample to a two-voxel layer. The

Figure 3 (a) Photograph of cross-section of sample after cutting at $Y=640$ mm. Indicated are the lateral sides (I and II) and the lamella numbers. A white line was added to the figure giving the definition of the simulated delamination with depth VD in the bonding plane B7 together with the position of transmitting (Tx) and receiving (Rx) elements. (b) Example of a nondestructive X-ray CT cut through the sample at $Y=240$ mm. The bonding plane numbers are indicated. A gap of approximately 2 mm is obvious in bonding planes B2 and B3. In lamellas No. 2 and 3, two dark line artifacts due to the presence of steel nails are visible (indicated by white arrows).

anisotropic properties of wood were treated as follows: first, an optic scan of a cross-section of the sample was obtained (Figure 3a), then the growth rings at each lamella were fitted to cylinders with centers C1...C14, and the stiffness tensor was locally transformed using the acoustic parameters of spruce from Hörig (1935). In the bonding plane B7, several simulations were run, each simulating a delamination with depth VD in the range of 0 mm to the full width in 10 mm steps. The pixel size was 0.2 mm and the time step was 0.2 μ s. The transducer was positioned over B7 with the three transmitting points (Tx) being on one side and the three receiving points (Rx) and on the other side of the delaminations (Figure 3a). The transmitting points (Tx) were implemented as point sources consisting of seven nonzero voxels defining a Gaussian window with $\sigma=0.1$ mm.

Results and discussion

X-ray CT

The main purpose of these measurements was the detection of structural details such as growth rings, nails, and

large gap delaminations. A 3D CT data set was acquired over the length range $Y=135\text{--}355\text{ mm}$. As an example, Figure 3b shows a cross-section at $Y=240\text{ mm}$. The individual lamellas and their growth ring structure are visible. Due to the limited dimensions of the CT equipment, two data sets had to be acquired to cover the whole cross-section with its height of 384 mm. In the center of lamella no. 7, the cross-sections were connected, which is visible in the image as a slight contrast discontinuity. Concerning delaminations, large gaps of approximately 2 mm are to be seen in bonding planes B2 and B3 over the complete cross-section. This delamination is both detected with the feeler gauge and by ultrasonic inspection (see next section). The present straightforward analysis of the CT data reveals large gaps more than 1 mm. More elaborate evaluations would have been necessary to take into account the amplitude modulation due to the growth rings and the nonplanarity of the glue lines. It is estimated that such a sophisticated data treatment could reveal gaps down to approximately 0.5 mm. A few internal steel nails were observed; some of their artifacts are also visible in Figure 3b (white arrows). Other delaminations were too thin to be visible in this image. Overall, the feeler gauge is thinner than the CT pixel size; thus, it is able to detect even thinner delaminations than CT will reveal.

Ultrasonic inspection

The first step of interpretation involves the identification of the ultrasonic echoes. Figure 4 displays the ultrasonic

results measured along the bonding plane B4 side II. Because the high-voltage pulse to the transmitter Tx leaks electromagnetically to the receiver Rx, a main bang is observed in the time range of $0\text{--}60\text{ }\mu\text{s}$. This peak is present also when the probe is lifted off the sample. In the case of good bonding near the surface, one observes the reception of the SW (Figure 4c). For C-scans, this feature is evaluated in the time range of $60\text{--}110\text{ }\mu\text{s}$ (thus excluding the main bang signal). Later in time, one observes the first back-wall echo (BW1), which is evaluated for C-scans in the time range of $230\text{--}310\text{ }\mu\text{s}$. At some Y-positions, a second back-wall echo (BW2) is observed. Obviously, at certain positions, the SW is present (Figure 4c), and at others, it is absent (Figure 4b). Also, the back-wall echo shows some variation with the Y-position. The wave propagation is influenced by the natural variability of wood. Relevant effects are, for example, variations in (a) mechanical properties between lamellas, (b) energy flux shifts from insonification direction that lead to partial fading at the receiver, (c) wave interference of waves transmitted through earlywood/latewood channels, and (d) wave scattering at knots and to a minor extent at nails (Sanabria 2012).

The whole picture of the SW amplitudes is given in the C-scans of Figures 5a and b for both sides I and II of the sample. The data were normalized to the maximum amplitude and are displayed logarithmically in a 40 dB amplitude range. The presence of bonding plane delaminations at the surface reduces the SW amplitude, which is obvious from Figure 6, where a selection of measurements at four bonding planes is displayed. The thin lines are the SW amplitudes as a function of the length position (Y) and

Figure 4 Ultrasonic data of scan along bonding plane B4, insonified from lateral side II. (a) B-scan along the length of the sample. (b) A-scan at position 700 mm. (c) A-scan at position 300 mm. MB, main bang; SW, surface wave; BW1, first back-wall echo; BW2, second back-wall echo.

Figure 5 Ultrasonic C-scans of SW echo (60–110 μ s): (a) side I and (b) side II. Comparison between ultrasonic surface echo amplitude with delamination depth measured with feeler gauge (black lines: echo amplitude < -22 dB, gray lines: delamination depth ≥ 20 mm): (a') side I and (b') side II. (c') Comparison between ultrasonic back-wall echo amplitude with delamination depth measured with feeler gauge (black lines: side II echo amplitude < -21 dB; gray lines: total delamination depth $> 80\%$ of total width). Abscissa, length position Y; ordinate, bonding plane number.

the thick lines are the results of the corresponding feeler gauge measurements of the delaminations. The correlation between the two measurement techniques is obvious and it is further displayed in Figure 7 for three bonding planes. The natural variability of the echo amplitude is approximately 15 dB (due to knots, other wood irregularities and surface imperfections). From 0 to 20 mm deep delaminations, there is an amplitude drop from 0 down

to -20 dB. For deeper delaminations, the drop levels off at approximately -30 dB corresponding to the noise floor of the electronics. There are a few outliers at large delaminations where the measured SW amplitude seems to be too large; if one has a closer look to Figure 6c, one realizes that there is a short (20 mm long) full delamination at $Y=230$ mm. This delamination, however, is too short to be measured with the used transducer array, which has

Figure 6 Comparison of ultrasonic surface echo amplitude (thin line) and depth of delaminations measured with feeler gauge (thick lines). Arrows point to the appropriate axes. (a) Bonding plane B9 side I. (b) Bonding plane B11 side I. (c) Bonding plane B3 side II. (d) Bonding plane B5 side II.

a total length of 60 mm (four point probes with separation of 20 mm; see Figure 2b). Moreover, the wavelength along the longitudinal direction is approximately 120 mm [$f=50$ kHz and $c=5800$ m s⁻¹ (Hörig 1935)], which gives an

Figure 7 Correlation between ultrasonic surface echo amplitude with delamination depth measured with feeler gauge for three different bonding planes (open triangles: B11 side I, open squares: B3 side II, and filled squares: B5 side II). The scattering of the amplitudes of approximately 15 dB is due to the natural variability (knots, other wood irregularities, and surface imperfections). The continuous curve reflects the main trendline. It was determined with a clustering algorithm (20 consecutive points).

order of magnitude for the lateral resolution along the fiber direction. An overview and a comparison of the results of both measurement techniques are given in Figure 5a' and b'. It shows as black lines the positions where the SW amplitude is below -22 dB together with gray lines where the delamination depth measured with the feeler gauge exceeds 20 mm. On both sides, there is a good agreement (~80%) between the two measurement techniques. Gaps down to the detection limits by the feeler gauge (100 μ m) were easily visible. According to simulations (Sanabria 2012), gaps of 10 μ m still provide a contrast more than 20 dB based on longitudinal waves. Shear wave propagation is essentially not supported by fluid media; thus, a higher contrast is to be expected (Krautkrämer and Krautkrämer 1986). Therefore, in practice, delaminations are expected to be detected as long as a physical separation between lamellas exists.

Glue line delaminations are also expected to reduce the back-wall echo, which could be verified in the preliminary study of Sanabria et al. (2011c) on a test block with artificial flaws. The reduction of the echoes, however, was less pronounced compared with the SW. Similar results are found on the present glulam block with natural delaminations. Again, the ultrasonic results are compared with the feeler gauge data (Figure 5c'). Large (>80% of the bonding width) delaminations as found by the feeler gauge are

also indicated by a reduced back-wall echo (< -21 dB). However, the ultrasonic data reveal additional positions with reduced amplitudes. Large signal attenuation values caused by the heterogeneous material structure can lead to false defect hits. The main anatomic features introducing ultrasound were qualitatively identified in the X-ray CT images. The year ring structure leads to uncertainties in the wave propagation paths, which lead to amplitude fading at the receiver. The higher the ring curvature, the more critical are these effects. Wood knots and strongly cracked solid wood lamellas introduce additional scattering in the ultrasound fields. The metallic nail elements introduced a negligible scattering amount.

Numerical simulation

To understand the experimental results in more detail, numerical simulations of the wave propagation were

performed for the specific cross-section at $Y=640$ mm for several depths of delaminations in bonding plane B7. Figures 8a–d display time snapshots of the wave propagation at four successive instants for a delamination depth of 20 mm. At $30\text{ }\mu\text{s}$ (a), one perceives the emerging waves from the three transmitter points, which then, at $91\text{ }\mu\text{s}$ (b), have propagated into the bulk and diffracted around the delamination tip to reach the surface. The SW propagates further (c), and in the image at $250\text{ }\mu\text{s}$ (d), the main bulk wave is bounced back from the back-wall (BW1) toward the receiver Rx.

For simulating the receiver signal Rx, the time signals at the three individual receiver positions were added, giving, for example, the A-scan shown in Figure 8e, where the SW and two back-wall echoes (BW1 and BW2) are discernible (depth of delamination = 0 mm). If there is a delamination present, part of the wave travels around the discontinuity giving the first echo (SW). The deeper the crack is the later the echo arrives at Rx and the

Figure 8 Results of numerical simulation of wave propagation. (a–d) Time snapshots of propagating wave in the glulam cross-section with a delamination depth of 20 mm. The SW and the back-wall reflection (BW1) are indicated (a) $30\text{ }\mu\text{s}$, (b) $91\text{ }\mu\text{s}$, (c) $122\text{ }\mu\text{s}$, and (d) $250\text{ }\mu\text{s}$. (e) A-scan of receiver Rx in the case of absence of delaminations. (f) B-scan presentation of results with delamination depth as ordinate.

Figure 9 Results of numerical simulation of wave propagation. Echo amplitude as a function of delamination depth. Solid dots: surface echo (SW); open dots: back-wall echo (BW1). The dashed line gives a linear fit of the experimental data from Figure 7 in the range of 5–30 mm.

smaller is the amplitude, mainly due to an increased diffraction loss. Concurrently, the back-wall echo is reduced in amplitude but much less pronounced. Figure 8f illustrates the detailed evolution of the surface and the back-wall echoes in function of the depth of the delaminations. Evaluating these data in the same intervals as applied for the experimental data (surface echo: 60–110 μ s, BW1: 230–310 μ s) leads to Figure 9. This shows that a 20 mm deep delamination reduces the SW amplitude by approximately -20 dB, which very much agrees with the experimental findings (Figure 7). For comparison, a linear fit of the experimental data in the range of 5–30 mm is added into Figure 9 (dashed line); the slope is -0.8 dB mm^{-1} . Deeper delaminations reduce the amplitude further, and at 60 mm, it is below -30 dB. In the experiment, the noise floor is reached already at -30 dB. The back-wall echo is reduced at a much lower rate with increasing delaminations depth. Only toward complete width delaminations it drops below -20 dB, being again in agreement with the experimental findings. The small back-wall echo reduction is hence much more sensitive to be masked by natural variability of the wood components. The slight structures in the curves (SW at 40 mm and BW1 at 140 mm) are due wave interference effects. The simulations were done assuming zero damping of the ultrasonic waves. The effect of damping on the results in Figure 9 would not be relevant and can be estimated separately. An attenuation coefficient of approximately 0.5 dB cm^{-1} for the shear horizontal waves can be obtained under the following conditions: two echoes are transmitted through

a 156-mm-wide laboratory glulam beam without delamination and the diffraction effects are corrected with the actual simulated amplitudes. The importance of the damping increases as a function of distances. However, for example, for a 40-mm-deep delamination, this would result in the surface echo to be only 3 dB smaller than the value of -23 dB in Figure 9. For the back-wall echo in the same figure, the effect is negligible as the sound path remains constant in the first approach. On the contrary, the absolute values of the amplitudes as shown in Figure 8 would be damped with increasing time.

Conclusion

It was demonstrated experimentally on a section of a 90-year-old glulam member, which contained delaminations, that point-contact ultrasonic imaging is well suited for detecting these delaminations. The size of the damages is also indicated to a certain degree. Flaw depths larger than 20 mm reduce the SW amplitude by more than -20 dB, which is beyond amplitude variations due to the natural variability of wood (15 dB) and thus is a significant hint for the presence of a delamination. The back-wall echo is also reduced, but it diagnoses only very deep delaminations (>80% gluing plane width). The results of the ultrasonic investigations were compared with detailed feeler gauge measurements and a reasonable good correlation was found between the data. The findings were additionally supported by X-ray CT measurements and numerical simulations of the wave propagation in the identical cross-section for varying delamination depths.

More sophisticated analysis of X-ray CT data is planned for further comparison with the ultrasonic results. This will be done especially in view of internal delaminations that are not accessible to the feeler gauge. *In situ* ultrasonic inspections are now to be performed. We envisage to address material variations with difference imaging or normalization with respect to reference sections.

Acknowledgements: This research was supported by the Swiss National Science Foundation under contract 200021-115920. The authors would like to acknowledge the support of Roman Furrer and Tino Loop for the ultrasonic data acquisition, Pascal Keller for the help with numerical simulations, and Daniel Heer and Roland Stäuble for the handling and cutting of the glulam sample.

Received November 14, 2012; accepted March 22, 2013; previously published online April 13, 2013

References

- Aicher, S., Dill-Langer, G., Stritzke, C. Qualitätsprüfung von Klebefugen in Brettschichtholz mittels Ultraschall, Jahresbericht MPA, Universität Stuttgart, Germany, 2010.
- Angst, V., Malo, K.A. (2010) Moisture induced stresses perpendicular to the grain in glulam: review and evaluation of the relative importance of models and parameters. *Holzforschung* 64:609–617.
- Blass, H.J., Frese, M. Schadensanalyse von Hallentragwerken aus Holz. Tech. Rep., Karlsruher Institut für Technologie (KIT), Karlsruhe, Germany, 2010.
- Bucur, V. Delamination in Wood, Wood Products and Wood-Based Composites. Springer, New York, USA, 2011.
- Casado, M., Acuña, L., Basterra, L.-A., Ramón-Cueto, G., Vecilla, D. (2012) Grading of structural timber of *Populus × euramericana* clone I-214. *Holzforschung* 66:633–638.
- Dietsch, P., Hösl, M. (2010) Mapping of cracks. In: *Methods for the Assessment of Timber Structures*, COST Action E55. Modelling of the Performance of Timber Structures. Eds. Dietsch, P., Köhler, J. TUM Munich, Germany. pp. 52–54.
- Dill-Langer, G., Bernauer, W., Aicher, S. (2005) Inspection of glue-lines of glued laminated timber by means of ultrasonic testing. In: *Proc. 14th Int. Symp. NDT Wood*, Eberswalde, Germany. pp. 49–60.
- Dimanche, M., Capretti, S., Del Senno, M., Facaoaru, I. (1994) Validation of theoretical approach for the detection of delamination in glued laminated beams. In: *1st Eur. Symp. NDE Wood*. University of Forestry and Wood Science, Sopron, Hungary. pp. 250–260.
- Divos, F. (2011) Delamination evaluation of in-service glulam beams and other structural members via ultrasonics. In: *Delamination in Wood, Wood Products and Wood-Based Composites*. Ed. Bucur, V. Springer, New York, USA. Chapter 17. pp. 353–364.
- Drossaert, F.H., Giannopoulos, A. (2007) Complex frequency shifted convolution PML for FDTD modelling of elastic waves. *Wave Motion* 44:593–604.
- EN 1330-4. (2010) Non-destructive testing—Terminology. Part 4: terms used in ultrasonic testing.
- Follrich, J., Stöckel, F., Konnerth, J. (2010) Macro- and micromechanical characterization of wood-adhesive bonds exposed to alternating climate conditions. *Holzforschung* 64:705–711.
- Garab, J., Toth, A., Szalai, J., Bejo, L., Divos, F. (2010) Evaluating glued laminated beams using a nondestructive testing technique. *Trans. Famena* 34:33–46.
- Hansson, M., Larson, H. (2005) Recent failure in glulam structures and their causes. *Eng. Fail. Anal.* 12:808–818.
- Hasenstab, A. (2006) Integritätsprüfung von Holz mit dem zerstörungsfreien Ultraschallechoverfahren, Dissertation (Ph.D. Thesis), Technische Universität Berlin, Germany.
- Hasenstab, A. (2007) Ultraschall-Echo zur Ortung von Rissen in Brettschichtholz (BSH). Tagungsband DGZfP Jahrestagung, Fürth, Germany.
- Hörig, H. (1935) Anwendung der Elastizitätstheorie anisotroper Körper auf Messungen an Holz. *Arch. Appl. Mech.* 6:8–14.
- Hu, L.J., Gagnon, S. (2007) X-ray based scanning technique for non-destructive evaluation of finger-joint strength. In: *Proc. 15th Int. Symp. NDT Wood*. Forest Products Society, Duluth, MN, USA.
- Jönsson, J.H. (2005) Internal stresses in glulam due to moisture gradients in the grain direction. *Holzforschung* 59:18–22.
- Konnerth, J., Gindl, W. (2008) Observation of the influence of temperature on the mechanical properties of wood adhesives by nanoindentation. *Holzforschung* 62:714–717.
- Krautkrämer, J., Krautkrämer, H. Werkstoffprüfung mit Ultraschall, Springer, Berlin, Germany, 1986.
- Niemz, P., Kucera, L.J., Flisch, A., Blaser, E. (1997) Application of computer tomography (CT) on wood defects and decay. *Eur. J. Wood Wood Prod.* 55:279–280.
- Saenger, E.H., Gold, N., Saphiro, S.A. (2000) Modeling the propagation of elastic waves using a modified finite-difference grid. *Wave Motion* 31:77–92.
- Sanabria, S.J. (2012) Air-coupled ultrasound propagation and novel non-destructive bonding quality assessment of timber composites, Dissertation (Ph.D. Thesis), No. 20404, ETH Zurich, Switzerland.
- Sanabria, S.J., Mueller, C., Neuenschwander, J., Niemz, P., Sennhauser, U. (2011a) Air-coupled ultrasound as an accurate and reproducible method for bonding assessment of glued timber. *Wood Sci. Technol.* 45:645–659.
- Sanabria, S.J., Furrer, R., Neuenschwander, J., Niemz, P., Sennhauser, U. (2011b) Air-coupled ultrasound inspection of glued laminated timber. *Holzforschung* 65:377–387.
- Sanabria, S.J., Furrer, R., Neuenschwander, J., Niemz, P., Sennhauser, U. (2011c) Monitored assessment of structural integrity of multilayered glued laminated timber beams with air-coupled ultrasound and contact ultrasound imaging. In: *17th International Nondestructive Testing and Evaluation of Wood Symposium*. University of West Hungary, Sopron, Hungary, Conf. Proc. pp. 359–366.
- Sanabria, S.J., Wyss, P., Neuenschwander, J., Niemz, P., Sennhauser, U. (2011d) Assessment of glued timber integrity by limited-angle microfocus X-ray computed tomography. *Eur. J. Wood Prod.* 69:605–617.